

Envelope Repairs

Administration Building

This project is part of the ongoing envelope upgrades at the 1909 Administration Building on the University of Idaho Campus. Upgrades include

- exterior clay brick and cast stone masonry restoration and repair
- replacing sealant around exterior windows and doors
- repairing roof leaks via replacement and repair
- cleaning and refinishing exterior marble flooring at east entrance
- ADA upgrades to the southwest building entrance
- replacing non-code compliant handrails at east entrance
- and fabricating and installing new cast stone finials to replace the original finials that were removed over time

CSHQA Architects is the project architect.



Figure 1 Window well



Figure 2 Deterioration at stairs



Figure 3 Window well



Figure 4 Roof & finial